

Playground Repairs 7 to 10 May 2026

Gate latch, paling and stop fixed. (Note need another paling.)



Tower slide board missing and replaced.



All crossbeam members tightened all the way round, excess bolt threads ground off, and missing covers replaced.



Climbing wall handgrips tightened. Bottom fastening packed and tightened. (Note some screws need to be replaced. Ideally a new climbing wall board is required.)



Rusty screws on Zip wire platform fence replaced and all other screws tightened.



Gate post temporarily repaired. Steel angle support fastened to fence. Need to add another post where the steel support is to make a rigid repair that should last for a few years. Latch replaced and hinge repositioned on the double gate.



Double gate hardware replaced with more robust fittings. Missing paling replaced. Palings screwed in place where necessary. Gate height adjusted.

